

S.A.F.E.R. & A.B.C.

S for Speed – The rotational speed should be slower for big & heavy items and faster for smaller lighter things. Check the speed is compatible with the size of blank to be turned.

A for Aside – Stand to the side of the blank's 'firing line' (not in front of the blank).

F for Fixings – Confirm that all materials and equipment, tool-rest, tailstock, etc. are correctly attached and secure.

E for Eyes – wear a safety visor or protective goggles.


R for Revolve – Confirm the blank can freely rotate without encountering any obstructions such as the tool rest.

A.B.C

A = Anchor

B = Bevel

C = Cut



IMPORTANT

Never use the indexing pin to lock the spindle when removing a chuck or faceplate.

Always use the spanners provided.